

Release Notes for Version 2.17

In the interest of ongoing product development and improvement, Bosch is proud to release software version 2.17 for the Solution 6000 Security Control Panel. This document briefly outlines the new features and improvements added in this release. Please read in conjunction with the current installation manual and other addendum's for more detailed information.

➔ CM720B 1 Amp Power Supply Battery Trouble

1) CM720B 1 Amp Power Supply > Battery Trouble

In previous versions, the control panel may fail to clear a battery trouble condition even though the trouble condition has been rectified. This issue only occurs when using CM720B power supplies with V2.14 firmware.

In version 2.17 of the panel code, an installer or master user can use MENU 7-9-1 - Test Battery to manually force the control panel to perform a battery test on both the control panel and the 1 Amp power supply and this will clear the trouble condition provided the backup battery is normal.

2) History Log Sequence Number Fix

The V2.17 release fixes an issue where the history log sequence number that is shown in SolutionLink could become out of sync with the panel's sequence number.

3) Various Improvements And Additions Added

The V2.17 release includes a number of internal improvements and additions that will help it to support upcoming features due for release later in the year.